1.3 Flame Scanners



IR Self Check Scanner

Item No.	Flame Scanners	Kgs	Part No.
13	IR Self Check Scanner	0.20	MM70017
	For use with Mk8 MM, Mini Mk8 MM and Mk7 MM		



Self-Check UV Scanner, High Sensitivity, End View



Self-Check UV Scanner, High Sensitivity, Side View

Item No.	Flame Scanners	Kgs	Part No.
14	Self Check UV Scanner, High Sensitivity	0.80	MM60003/HS
	End view only, 1" connection		
15	Self Check UV Scanner, High Sensitivity	0.85	MM60003/HS/SV
	Side view only		



Standard UV Scanner, Side View



New Side View UV Scanner



Standard UV Scanner, End View



Swivel Mount Assembly, 1" connection

Item No.	Flame Scanners	Kgs	Part No.
16	New Side View UV Scanner	0.20	MM80004
	Complete with clip and plate connection		
1 <i>7</i>	Standard UV Scanner (Limited Availability)	0.20	MM60004
	Side view only, complete with clip and plate connection		
18	Standard UV Scanner	0.20	MM60004/U
	End view only, ½" connection		
19	Standard UV Scanner, High Sensitivity	0.20	MM60004/HSU
	End view only, ½" connection		
20	Swivel Mount Assembly, 1" connection	1.50	UVM60003
	Mounting adaptor for optimum positioning of UV scanner		
21	Swivel Mount Assembly, 1/2" connection	1.50	UVM60004
	Mounting adaptor for optimum positioning of UV scanner		